Structure No: GER-070-03.37 SFN: 0631671 Old Bridge No.: GER 30 NBIS Bridge Length: Yes Road Name: CR 70 Lock Two Road Koop Creek Feature Intersected: Latitude: N40°27'05.5" Height Above Stream: 8'-0" Longitude: W84°23'19.7" **SUPERSTRUCTURE** StructureType: County beam Year Built: 1987 **Bridge Limits:** Spans: 29'-1" 31.00' Ohio Legal Load: 180% Rdwy. Width: Contractor: Auglaize County 24'-0" Design Load: HS20-44 Total Width: 25'-6" Fabricator: Auglaize County Skew: LF 32°30' G.R. Type: Deep beam Turndown G.R.: Yes Wear. Surface: **Asphalt Concrete** Deck Type: None Drainage: Over the sides (without drip strip) Waterproofing: GeoTac in 2007 Sidewalks: **Expansion Joints: None** None Type of Beams: 8-14"x36" Bearings: 1/2" rubber Minimum Clearances - Left: Right: 2'-0" Vertical: 99'-99" 2'-0" Max. Vert.: 99'-99" General Condition: Plans: Sketch Construction Cost: \$10,734.32 5A Sufficiency Rating: 70.9 Postings: None Year: None **SUBSTRUCTURES** Year Built: 1962 Contractor: Unknown Material Type Wall Size Footing/Piling Rear Abut.: Reinforced Conc. Solid Wall 1'-6"x9'-0" Footer 1'-6"x9'-0" Fwd. Abut.: Reinforced Conc. Solid Wall Footer Pier 1: Pier 2: Pier 3: Pier 4: NAD1929 Benchmark: Top step NW wingwall Elev. 927.26 #### 1987-Minor repair work done to the abutments to support new superstructure. G R: E E: N M:

E A:

L /1.

R R:

A K:

L S:

####

Flood Data

Drainage Area:

3.66 Sq. Miles

1980 Flood Data:

1992 H.W. Elev. 925.5

1993 H.W. Elev. 926.6

2011 H.W. Elev. 926.45

Structure No: GER-070-03.37

CR 70 Lock Two Road

Utilities

Within Right-of Way: ET

Electric: Dayton Power & Light Co.

Gas: None

On Structure: None

Telephone: Frontier

Other: None

Maintenance Records

2004- The bridge and approaches were paved

2007- Both exterior beams were replaced due to deterioration and deck waterproofed at a cost of \$13,101.36

2008 - A car rode up the southwest turndown guardrail. County repaired most of the damage.