BORNHORST SURVEY
Part of the NW 1/4 of Sec. 33, T75, R4E,
Jackson Twp., Auglaize Co., Ohio



D=1P in Hon. Bx b= RRSPk Fd

6 = 5/8" Rebar Set


Mark & Mary Bornhorst Vol. 9 Fg. 185

|               | DUE                                  | EAST                                    |                |                                 |       |
|---------------|--------------------------------------|---|----------------|---------------------------------|-------|
|               | 220,46'                              | 220.45                                  | *a             |                                 |       |
| X10:38'.30" E | Tract "A"  1.229 Ac  0.127 Ac in P/W | 10, 10, 10, 10, 10, 10, 10, 10, 10, 10, | 0.             | Steve<br>Kemper<br>1.115 Ac     |       |
| 25' \$        | 2/W Line Y<br>220.46'                | 220.4<br>WEST                           | S' Minster - E | 1/2 Sec Line<br>Egypt Rd (RdNº2 | ?6) 1 |

Surveyed: 11 March, 1989

William G. Fultz, Jr.

Reg. Surveyor Nº 5173



J-534

(T\_7\_S; R\_4\_E)

| Signature by a representative of the County Health Dept. denotes compliance with Health Regulations.  Signed:  | Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat.  Signed:  Date    |  |  |
|--|--|--|--|
| Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed: | Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements.  Signed: Date |  |  |
| Client<br>County<br>Drawn by<br>Checked by   | Mark J. # Mary E. Bornhorst  Uglaize Twp. Jacksorn Sec. 33  Scale 1'=100' Drwg. No'  Date 3/11/89                                  |  |  |

Checked by \_\_\_\_\_Sheet\_\_ / \_of\_\_ /

## William G. Fultz, Jr. & Associates

PROFESSIONAL SURVEYOR 819 LORI COURT SIDNEY, OHIO 45365 (513) 492-9674

## BORNHORST DESCRIPTION TRACT "A"

Part of the NW 1/4 of Sec.33, T7S, R4E, Jackson Twp., Auglaize Co., Ohio:

Commencing at an iron pin set in a monument box in the southwest corner of the northwest quarter of said section 33; thence Due East, along the south line of said northwest quarter (Minster-Egypt Rd.), 25.00 ft. to a RR Spike and the place of beginning for the following described real estate:

Thence  $NO^{\circ}$ -38'-30"E, 242.81 ft. to an iron pin;

Thence Due East, 220.46 ft. to an iron pin;

Thence  $S0^{\circ}$ -38'-30"W, 242.81 ft. to a RR Spike on the south line of said northwest quarter;

Thence Due West, along said south line, 220.46 ft. to the place of beginning.

Containing 1.229 Ac. more or less, being subject to all legal highways and easements of record, and being part of the premises recorded in Vol.9 Pg.185 of the Auglaize Co. Deed Records.

This description prepared from a field survey made by William G. Fultz, Jr. on March 11, 1989.

William G. Fultz, Jr.

Reg. Surveyor No.5173

## William G. Fultz, Jr. & Associates

PROFESSIONAL SURVEYOR 819 LORI COURT SIDNEY, OHIO 45365 (513) 492-9674

## BORNHORST DESCRIPTION TRACT "B"

Part of the NW 1/4 of Sec.33, T7S, R4E, Jackson Twp., Auglaize Co., Ohio:

Commencing at an iron pin set in a monument box in the southwest corner of the northwest quarter of said section 33; thence Due East, along the south line of said northwest quarter (Minster-Egypt Rd.), 245.46 ft. to a RR Spike and the place of beginning for the following described real estate:

Thence  $NO^{\circ}$ -38'-30"E, 242.81 ft. to an iron pin;

Thence Due East, 220.45 ft. to an iron pin;

Thence SO -38:-30"W, 242.81 ft. to a RR Spike on the south line of said northwest quarter;

Thence Due West, along said south line, 220.45 ft. to the place of beginning.

Containing 1.229 Ac. more or less, being subject to all legal highways and easements of record, and being part of the premises recorded in Vol.9 Pg.185 of the Auglaize Co. Deed Records.

This description prepared from a field survey made by William G. Fultz, Jr. on March 11, 1989.

William G. Fultz, Jr.

Reg. Surveyor No.5173