


Fairmount, Cemetery Assn.
D.V. 112, Pg 200

- B = Monument Box at the northwest corner of Section 15
- C = Monument Box at the Intersection of Fairmount Rd. & Boundary Rd.
- D = Existing PK nail
- E = Existing #5 rebar
- G = Existing RR spike at the N1/4 post of Section 15
- J = Existing Mag nail
- K = Existing 3/4" pipe



Clayton T. Bacon, Reg. P.S. #6179 4-20-05

This description and plat is based on an actual field survey performed on 11-19-01, by Bacon & Associates under the direction of Clayton T. Bacon, P.S. #6179

Prepared By
Bacon & Associates, L.L.C.
750 N. Eastown Rd., Elida, Ohio 45807
Office: (419) 999-3756 - Fax: (419) 999-2522

Mr. Jerry Winegardner
SW1/4, NW1/4, Section 15, T5S, R7E
Union Township, Auglaize County, Ohio.

File:
122-05

Revisions: _____

Drawn: msh Date: 4-18-05

Bacon & Associates

Engineering and Surveying

750 N. Eastown Road

Phone: (419) 999-3756

Elida, Ohio 45807

FAX: (419) 999-2523

Description

Being a parcel of land in the NW $\frac{1}{4}$ of Section 15, T5S, R7E, Union Township, Auglaize County, Ohio, more particularly described as follows:


Beginning at an existing RR spike marking the N $\frac{1}{4}$ post of Section 15, thence the following courses;

1. S.0°-20'-10"W. on the east line of the NW $\frac{1}{4}$ of Section 15, 1324.07' to a set #5 rebar at the southeast corner of the NE $\frac{1}{4}$ of the NW $\frac{1}{4}$ of Section 15, passing over a set #5 rebar at 30.00';
2. N.89°-25'-52"W. on the south line of the NE $\frac{1}{4}$ of the NW $\frac{1}{4}$, 1262.44' to a set Mag nail on the centerline of Boundary Road, passing over a set #5 rebar at 1237.44';
3. S.0°-03'-41"W. on the centerline of Boundary Road, 371.66' to an existing Mag nail;
4. N.89°-22'-58"W., 1391.58' to an existing #5 rebar, passing over an existing #5 rebar at 25.00';
5. N.0°-37'-02"E. on said west line, 1794.09' to the monument box at the northwest corner of Section 15;
6. S.85°-14'-49"E. on the north line of the W $\frac{1}{2}$ of the NW $\frac{1}{4}$ (centerline Fairmount Road), 1378.73' to the monument box at the intersection of the centerlines of Fairmount Road and Boundary Road;
7. S.0°-03'-41"W. on the centerline of Boundary Road, 217.81' to an existing PK nail;
8. S.89°-28'-39"E., 400.00' to an existing $\frac{3}{4}$ " pipe, passing over an existing $\frac{3}{4}$ " pipe at 30.00';
9. N.0°-03'-41"E., 217.81' to an existing PK nail on the north line of the E $\frac{1}{2}$ of the NW $\frac{1}{4}$ (centerline Fairmount Road), passing over an existing $\frac{3}{4}$ " pipe at 187.81';
10. S.89°-28'-39"E. on said north line, 868.79' to the RR spike at the POINT OF BEGINNING.

The above-described parcel contains 91.843 acres, more or less, subject to all legal highways and easements of record at the time of this survey.

A bearing of S.0°-03'-41"W. was assumed for the east line of the W $\frac{1}{2}$ of the NW $\frac{1}{4}$ (centerline of Boundary Road).

This description and plat are based on an actual field survey performed on 11-19-01 by Bacon & Associates L.L.C., Clayton T. Bacon, P.S. #6179.



Clayton T. Bacon
4-20-05