

750 N. Eastown Rd., Elida, Ohio 45807 Office: (419) 999-3756 - Fax: (419) 999-2523 Associates,  $\mathcal{J}acon$ 

Ohio

County,

Auglaize

Township,

2

Ma

0

 $\hat{\mathcal{N}}$ 

ection

X U C K

D

Ū

400

200

C - Monument Box at the southeast corner of Section 12

D - Existing Section Stone at S1/4 post, Section 12


G - Monument Box at the W1/4 post, of Section 12

H - Existing ODOT #5 rebar at N1/4 post, of Section 12

J - Existing Section stone at the E1/4 post, of Section 12

M - Set #5 rebar calculated center of Section 12

> File: 527-03 Date: 11-24-03



Engineering and Surveying

750 N. Eastown Road

Phone: (419) 999-3756 FAX: (419) 999-2523 Elida, Ohio 45807

## DESCRIPTION (Business)

Being a parcel of land in the SE¼ of Section 12, T6S, R4E, St. Marys Township, Auglaize County, Ohio, more particularly described as follows:

Commencing for reference at the monument box at the southeast corner of Section 12, thence N.0°-11'-03"W. on the east line of the SE¼ of Section 12, 1258.93' to an existing PK nail on the centerline of SR 29; thence N.42°-04'-04"W. on the centerline of SR 29, 627.83' to a set Mag nail at the PT of a curve to the right; thence northwesterly on the centerline of SR 29, 184.67' to a set Mag nail at the POINT OF BEGINNING of the parcel to be described, said curve having a radius of 751.39' and an L.C. of N.35°-01'-34"W., 184.21'; thence the following courses;

- 1. S.89°-20'-00"W., 1038.66' to a set #5 rebar, passing over a set #5 rebar on the west R/W of SR 29 at 33.60';
- 2. S.0°-39'-59"E., 551.33' to a set #5 rebar;
- 3. S.84°-56'-27"W., 105.02' to a set #5 rebar;
- 4. S.89°-20'-00"W., 192.78' to a set #5 rebar;
- 5. N.1°-03'-21"W., 1045.66' to a set #5 rebar;
- 6. N.89°-18'-11"E., 1159.74' to a set Mag nail on the centerline of SR 29, passing over a set #5 rebar at 1127.83' on the west line of SR29;
- 7. S.20°-38'-21"E. on the centerline of SR 29, 424.20' to a set Mag nail at the P.C. of a curve to the left.
- 8. Southeasterly on the centerline of SR 29, 96.34' to the P.O.B., said curve having a radius of 751.39' and an L.C. of S.24°-18'-49"E., 96.28'.

The above-described parcel contains 17.747 acres, more or less, subject to all legal highways and easements of record at the time of survey.

A bearing of N.0°-11'-03"W. was assumed bearing the east line of the SE¼ of Section 12.

This plat and description is based on a field survey on 10-29-03 by, Bacon & Associates, LLC under the direction of Clayton T. Bacon, P.S. #6179.

STM-12-5A

Clayton J. Bacon 9-3-04 Engineering and Surveying

750 N. Eastown Road

Phone: (419) 999-3756 FAX: (419) 999-2523 Elida, Ohio 45807

## DESCRIPTION (Ted Kuck)

Being a parcel of land in the SE¼ of Section 12, T6S, R4E, St. Marys Township, Auglaize County, Ohio, more particularly described as follows:

Commencing for reference at the monument box at the southeast corner of Section 12, thence N.0°-11'-03"W. on the east line of the SE¼ of Section 12, 1258.93' to an existing PK nail on the centerline of SR 29; thence N.42°-04'-04"W. on the centerline of SR 29, 93.92' to a set Mag nail at the POINT OF BEGINNING of the parcel to be described, thence the following courses;

- 1. S.89°-20'-00"W. on the south line of the NE¼ of the SE¼ of Section 12, 1273.70' to a set #5 rebar at the southwest corner of the NE¼ of the SE¼ of Section 12, passing over a set #5 rebar at 39.99';
- 2. S.0°-09'-45"W. on the east line of the SW $\frac{1}{4}$  of the SE $\frac{1}{4}$ , 1328.67' to a set #5 rebar at the southeast corner of the SW $\frac{1}{4}$  of the SE $\frac{1}{4}$ ;
- 3. N.89°-21'-50"W. on the south line of the SE¼ of Section 12, 1336.90' to an existing section stone at the S¼ post of Section 12, passing over a set #5 rebar at 722.23' and at 943.90';
- 4. N.0°-08'-31"W. on the west line of the SE¼ of Section 12, 2655.94' to a set #5 rebar at the center of Section 12;
- 5. N.89°-18'-11"E. on the north line of the SE¼ of Section 12, 1852.21' to a set Mag nail on the centerline of SR 29, passing over a set #5 rebar at 1820.29';
- 6. S.20°-21'-21"E. on the centerline of SR 29, 1.88' to an existing RR spike at the PI of SR 29 centerline Sta. 359+14.62;
- 7. S.20°-38'-21"E. on the centerline of S.R. 29, 306.10' to a set Mag nail;
- 8. S.89°-18'-11"W., 1159.74' to a set #5 rebar, passing over a set #5 rebar at 31.91';
- 9. S.1°-03'-21"E., 1045.66' to a set #5 rebar;
- 10. N.89°-20'-00"E., 192.78' to a set #5 rebar;
- 11. N.84°-56'-27"E., 105.02' to a set #5 rebar;
- 12. N.0°-39'-59"W., 551.33' to a set #5 rebar;
- 13. N.89°-20'-00"E., 1038.65' to a set #5 rebar, passing over a set #5 rebar at 1005.05';
- 14. Southeasterly on the centerline of SR 29 on a curve to the left, 184.67' to a set mag nail at the P.T., said curve having a radius of 751.39' and an L.C. of S.35°-01'-34"E., 184.21';

5TM-12-5B

15. S.42°-04'-04"E.on the centerline of SR 29, 533.91' to a set Mag nail at the intersection with the south line of the NE¼ of the SE¼ of Section 29, the POINT OF BEGINNING.

The above-described parcel contains 56.250 acres, more or less, subject to all legal highways and easements of record at the time of survey.

A bearing of  $N.0^{\circ}$ -11'-03"W. was assumed for the east line of the SE¼ of Section 12.

This plat and description is based on a field survey on 10-29-03 by, Bacon & Associates, LLC under the direction of Clayton T. Bacon, P.S. #6179.

Clayton J. Bacon 9-3-04