KOCH TO GLACIER ESTATES, LLC. SURVEY 0.138 Acres being a part of the Northeast Quarter of Section 15, Pusheta Township, Town-6-South, Range-6-East, County of Auglaize, State of Ohio LEGEND Iron Pipe (found) TRAVERSE TABLE Iron Pin (found) (A) S. 38°-44'-24" E. 146.15 Monument Box S. 80°-12'-09" W. 94.00 Railroad Spike (found) N. 00°-30'-53" E. 130.00 Northwest Corner, East Half, Northeast Quarter, PUSHETA R O A D₁ (T. R. 120) Section 15, Pusheta Twp. S. 89°-09'-29" E. 1.328.22' Northwest Northeast Section 15, LOCATION PLAN LESTER & MARY KOCH PUSHETA RD. VOL OR 534 Corner, Pusheta PG 1602 18 CEMETERY FREYBURG FREYBURG DRIVE Section 15, Pusheta Twp. Auglaize County, Ohio BRUCE & TRACY SCHUMANN VOL OR 271 PG 673 **SCALE** (C)ATTEST N. 80°-12'-09" E. NOTE: Iron Pipe (found) at N. 80°-12'-09" E. (B) and 1.52 feet from Ted K. Schnell calculated corner Professional Engineer Professional Surveyor 0FGLACIER ESTATES, LLC TED VOL OR 568 KEVIN KEVIN PG 353 SCHNELL SCHNELL 51963 7216 Southwest Corner, East Half, Northeast Quarter, Section 15, Pusheta Twp. ONAL NOTES H & S Civil Engineers and Land Surveyors The Basis of Bearings used for this Survey was determined from the Auglaize County Engineer's GPS Survey. 45895 This Survey Plat is Recorded in Survey Book _ GLACIER HILLS SANITARY PLANT 15 Page 142, Auglaize County Engineer's Tax Map Office. 08/04/08 **PUSHETA AUGLAIZE** OHIO Map Office.