





Plat of a Survey  
in the S.E. 1/4 of Section 22,  
and  
the S.W. 1/4 of Section 23,  
T4S - R5E, Logan Township,  
Auglaize County, Ohio

Thomas C. Hubbell  
Reg. Surveyor #5044



NOTE: I.P. INDICATES IRON PIN

SHELDON ENGINEERING

LIMA, OHIO

|               |      |         |           |
|---------------|------|---------|-----------|
| SEPT. 5, 1972 | DATE | JOB NO. | 7902      |
| DRAWN         | 08   | CHECKED |           |
| APPROVED      |      | SCALE   | 1" = 100' |