


PLAT OF A SURVEY OF LOT 21 IN HICKORY HILL SUBDIVISION IN SECTION 35 MOULTON TOWNSHIP AUGLAIZE COUNTY, OHIO



Robert E. Chambers
ROBERT E. CHAMBERS
REG. SURVEYOR #6081

SOUTH LINE OF COUNTY RD. 33-A AS ESTABLISHED BY A
STRAIGHT LINE BEING THE LINE BETWEEN THE 1/2" CONCRETE RIGHT-OF-WAY MON-
UMENT FOUND FOR STATION 64+00-155 W. & STATION
64+400-155 W.

Due to the absence of substantial amount of original hardwood stakes as noted in the recorded
survey of the Hickory Hill Subdivision I held the State of Ohio concrete monumentation of the south
right-of-way of the County Road 33-A to set the north limits of the platted lots 1, 11 and 21.
40.00 feet wide roadway retained between said south right-of-way and north lot line of Lot 21.

The east-west positioning was set by a concrete monument found to be accepted on the east line
of said subdivision and 38.64 feet south from the south right-of-way of County Road 33-A.

This plat represents the positioning of various monuments and the relationship to this plat
calculated lot corners.

PREPARED: APRIL 25, 1989
BY: SHELDON B. ASSOC. INC.
1280 N. COLE ST.
LIMA, OHIO