



1

1

NOTE: There is an average of approximately 3.8' between the centerline of Cherry Street and the centerline of South Street (as occupied). In this surveyor's opinion, this average should not be proportioned, based upon the existing lines of occupancy, for any reason, the centerline of South Street (as occupied) is 3.3' south of the actual centerline. It is clear that a court of law would have several options, but I feel the one approach taken in this survey is the most equitable.



SURVEYED BY *Gordon L. Geeslin*
GORDON L. GEESLIN
REGISTERED SURVEYOR
NO. 5372



LEGEND

"A" = P.K. NAIL FOUND.
"B" = P.K. NAIL SET.
"C" = 5/8" IRON BAR SET.

SURVEY OF LOTS 377, 376, AND ALL
OF LOT 375 EXCEPT THE NORTHERLY 55'
IN THE VILLAGE OF NEW BREMEN,
AUGLAIZE COUNTY, OHIO.

AUGUST, 1974

SCALE 1"=100'

Signature by a representative of the County Engineer's Dept.
denotes that this plat meets tax map plat requirements.

Signed: _____ Date: _____

Signature by a representative of the County Commissioner(s)
denotes approval of this plat.

Signed: _____ Date: _____

Signature by a representative of the County Health Dept.
denotes compliance with Health Regulations.

Signed: _____ Date: _____

Signature by a representative of the Auglaize County Regional
Planning Commission denotes approval of this plat.

Signed: _____ Date: _____

GORDON GEESLIN
REG. SURVEYOR

154

Client ROMAN STUEDE

County AUGLAIZE Twp. GERMAN Sec. 15

Drawn by GG Scale 1"=100' Drwg. No. _____

Checked by GG Date AUG. 8, 1974

Sheet 1 of 1 (T 7 S 15 R 4 E)

154