


KOHLI AND KALIHAR ASSOCIATES, LIMITED
CONSULTING ENGINEERS AND SURVEYORS
311 E. MARKET ST. — LIMA, OHIO 45801

CLIENT DORTHY AMBURGEY
COUNTY AUGLAIZE TOWNSHIP UNION
SECTION 23 LOT NO. _____
SUBDIVISION PART OF THE N.E. 1/4
DATE 3-16-72 COMPUTED BY T.A.M. SURVEYED BY T.J.M.
SHEET NO. 1 OF 1



Being a parcel of land situate in the northeast quarter of Section 23, T-5-S, R-7-E, Union Township, Auglaize County, Ohio, more particularly described as follows:

Commencing at the intersection of the west line of the northeast quarter of Section 23 and the north line of Section 23 (centerline of S.R. 67); thence EAST with said north line 641.50 feet; thence S 00° 02' 30"E, 430.00 feet to THE PLACE OF BEGINNING; thence S 89° 15' 10"E, 363.90 feet; thence S 00° 02' 30"E, 1961.31 feet; thence N 89° 41' 30"W, 363.90 feet; thence N 00° 02' 30"W, 1964.10 feet to the PLACE OF BEGINNING, containing 16.395 acres more or less and subject to all legal highways and other easements of record.

Theresa A. Mitzen
Reg. Surveyor