



SURVEY OF LOT #8
HARDING SUBD #1 P.B."B" & 59
405 SUNRISE ST.
CRIDERSVILLE OH



AT POINTS ①, ② & ③ ANGLE IRON POST WERE FOUND APPROX 6" EAST OF ACTUAL CORNER

NOTE: ALL OF THE IRON PINS & PIPE FOUND WERE 3" to 6" BELOW GRADE. ALL WERE CONSIDERED TO BE SET AT THE SAME TIME. AN ERROR of 0.35' E & W & 0.15' N & S EXISTS WITHIN THE PLAT. HELD CORNERS AS ORIGINALLY SET.

CRIDER-HEIGHTS SUBD #1

Signature by a representative of the County Health Dept. denotes compliance with Health Regulations.
Signed: N/A Date: N/A

Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat.
Signed: N/A Date: N/A

Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed: N/A Date: N/A

Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements.
Signed: N/A Date: N/A

Thomas W. Steinke & Assoc., Inc.
Land Surveying
123 West Auglaize St.
Wapakoneta, Ohio 45895

Client: ROBERT OGG
County: AUGLAIZE
Twp.: DUCHOUQUET
Scale: 1" = 60' DWG. NO. 1104
Drawn by: JES
Checked by: JES
Date: JUNE 2 1980
Sheet 1 of 1 (T 4 S: R 6 E)