

SURVEYORS DESCRIPTION

The following described tract of land is part of the northwest quarter of the northwest quarter of section 22, T5S,R7E, Union Township, Auglaize County, Ohio, and is more particularly described as follows.

Commencing at a capped nail at the northwest corner of the northwest quarter of section 22, Union Township. (capped nail being in the center of state route 67) Inence in a easterly direction along the center of State Route 67, 527.00 feet to a P-K nail, this being the PLACE OF DEJINNING.

Thence continuing easterly along the centerline of State Route 67, 100.00 feet to a P-K nail.

Thence in a southerly direction with an internal angle of 92°49' (passing through an iron pipe set at 30.00 feet) 324.00 feet to an iron pipe.

Thence in a westerly direction with an internal angle of 87° 11', 279.00 feet to an iron pipe.

Thence in a northerly direction with an internal angle of 92°49', 80.00 feet to an iron pipe.

Thence in a easterly direction with an internal angle of 87°111, 179.00 feet to a 6" wood post.

Thence in a northerly direction with an internal angle of 272°49' (passing through an iron pipe set at 214.00 feet) 244.00 feet to the P-K nail in the center of State Route 67, which was the PIACE OF BEGINAING.

The above described tract of land contains 1.071 acres more or less subject to all legal easements of record.

Signature by a representative of the County Health Dept. denotes compliance with Health Regulations. Signed:		Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat. Signed: Date
Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed:		Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements. Signed: Date Sharon Cummins
Franco (56470	Client Weiter Coscione To Lilburn Cummins County Signate Twp. Union Sec. 22	