

Auglaize County, Ohio more particularly described as follows:

at a PK nail found at the intersection of mection line of said Section 12 with the Route 1981 thence 8 26°37'15" E with maid 0 * Route 198, 1158.30 feet to a PK nail BEBINNING thence continuing 8.26°37'15" E 330.00 feet to a railroad spike biss centerline mouth maid Southwast quarter; south line (passing through a 5/8 inch at feet). feet 10 a 5/8 inch 99 ° 32' 22" 146.51 feet to a 5/8 inch thence 63 " 22' 45" assing through a 5/8 inch reber 301.45 at feet to the PLACE OF BESIMNING containing less and subject to all highway and 1 mon1 ints of record.

above description was prepared using an assumed bearing The for south line of the Northwest quarter of the Southeast

Signature by a representative of the County Health Dept, denotes compliance with Health Regulations, Signed: Date	Signature by a representative of the Auginize County Regional Planning Commission denotes approval of this plat. Signed: Date
Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees on Village with zoning jurisdiction denotes approval of this plat. Signed:	Signature by a representative of the County Engineer's Dept.
for political S. D. of:Date	denotes that this plat sepots tex map plat requirements. Riesed: