

LEGEND

A = Found RR spike
B = Set RR spike
C = Set #5 rebar


DESCRIPTION

Being a parcel of land in the NE $\frac{1}{4}$ of Section 13, T6S, R4E, St. Marys Township, Auglaize County, Ohio, More particularly described as follows:

Beginning at a found RR spike at the northeast corner of Section 13, thence the following courses;

1. S. 00°-00'-00" W. (assumed bearing) on the east line of Section 13 (being also the centerline of East Shelby Rd.), 510.00' to a set RR spike;
2. S. 89°-17'-25" W., 1320.61' to a set #5 rebar;
3. N. 00°-00'-00" E., 110.00' to a set #5 rebar;
4. S. 89°-17'-25" W., 494.39' to a set #5 rebar;
5. N. 00°-00'-00" E., 400.00' to a set #5 rebar;
6. N. 89°-17'-25" E., 1815.00' to the POINT OF BEGINNING.

The above described parcel contains 20.000 acres, more or less, subject to all legal highways and easements of record.



Clayton T. Bacon

Signature by a representative of the County Health Dept. denotes compliance with Health Regulations.
Signed: _____ Date: _____

Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat.
Signed: _____ Date: _____

Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed: _____ Date: _____
for political S. D. of: _____

Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements.
Signed: _____ Date: _____

BACON & ASSOCIATES
4600 Kitamat Tr.
Lima, Ohio 45805

Client Kuck Realty
County Auglaize Twp. St. Marys Sec. 13
Drawn by CTB Scale 1"=300' Drwg. No. _____
Checked by _____ Date 12-7-87
Sheet 1 of 1 H-184 (T 6 S; R 4 E)