

Commencing at a monument box found at the southwest corner of said Southeast quarter of said Section 9; thence N 00°00'00" E (assumed bearing) with the west line of said Southeast quarter, 1846.62 feet to a 5/8 inch rebar set and the PLACE OF BEGINNING thence continuing N 00°00'00" E with said west line, 270.00 feet to a 5/8 inch rebar set; thence S 50°00'00" E (passing through a PK mail set at 15.00 feet and a 5/8 inch rebar set at 35.00 feet). 337.73 feet to a 5/8 inch rebar set; thence S 00°00'00" W. 270.00 feet to a 5/8 inch rebar set; thence N 90°00'00" W (passing through a 5/8 inch rebar set at 302.73 feet and a PK mail set at 322.73 feet). 337.73 feet to the PLACE OF BEGINNING containing 2.093 acres more or less and subject to all highways and other legal easements of record.

I hereby certify the accompanying map and survey which it represents to be correct to the best of my knowledge and belief. All rebar set and called for are topped with a plastic Peramark cap stamped: KUCK & MORRISEY L.S. 6470.

Date: 4/21/90

LIMA, OHIO 45805 TELEPHONE 228-1735 - AREA CODE 419

2807 CHAPEL HILL DRIVE

Richard D. Morrisey, L.S. 5470 Kuck and Morrisey, Inc.

	PERSONAL SELECTION OF PROPERTY OF SELECTION	
Signature by a representative of the County Health Dept. denotes compliance with Health Regulations. Signed: Date		Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat. Signed: Date
		Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements. Signed: Date
KUCK and MORRISEY, INC. CONSULTING ENGINEERS & SURVEYORS LIMA, OHIO 45805	County	Frice Sproul % Mr. Ben Yale Attorney Duglar Twp. Wayne Sec. 2 PRAM Scale / "100" Drwg. No.

Checked by _______

Date

J-65

(T-5-S:R-8-E)