



The state of the s		
Signature by a representative of the County Health Dept. denotes compliance with Health Regulations. Signed: Date	Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat. Signed: Date	
Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed: for political S. D. of: Date	Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements. Signed: Date	
KUCK and MORRISEY INC	KRIDGE DEALTY C	

KUCK and MORRISEY, INC. CONSULTING ENGINEERS & SURVEYORS

LIMA, OHIO 45805 TELEPHONE 228-1735 - AREA CODE 419 2807 CHAPEL HILL DRIVE

Client <u>OAKRIDGE</u>	REALTY Co.	
County Auglaise	Two Salas	Sec 4
Drawn by RDM	Scale I'= >00	Drug No
checked by	Date	4/15/92
Sheet 1 of 2	J-15=	(T-5-S; R-4-E)
医克里氏氏征 医克尔氏氏征 医克里氏性 医二甲甲酰胺 医二氏试验 医大大性 医大大性 医大大性 医克里氏征		(- <u></u> 5, n_ <u>_</u>)





DESCRPTION

Being a parcel of land situate in the Northeast quarter of Section 4, T-5-S, R-4-E, Salem Township, Auglaize County, Ohio and more particularly described as follows:

BEGINNING at an iron pin found at the northeast corner of said Northeast quarter of said Section 4; thence N 89°30'00" W with the north line of said Northeast quarter (also the centerline of State Route 197), 786.92 feet to a railroad spike found; thence thence S 00°30'00" W (passing through a 5/8 inch rebar found at 20.00 feet), 350.00 feet; thence N 89°30'00" W, 250.00 feet to a 5/8 inch rebar found; thence N 00°30'00" E (passing through a 5/8 inch rebar found at 330.00 feet), 350.00 feet to a railroad spike found on the north line of said Northeast quarter; thence N 89 $^{\circ}$ 30 † 20 $^{\circ}$ W with said north line (also the centerline of S.R. 197), 304.39 feet to a PK nail set at the northwest corner of the east half of said Northeast quarter; thence S 00°11'37" W with the west line of the northeast quarter of said Northeast quarter, (passing through a 5/8 inch rebar set at 20.00 feet), 1376.56 feet to a 5/8 inch rebar set; thence S 89°22'33" E (passing through a 5/8 inch rebar at the top of the bank of an open ditch at 445.91 feet), 457.89 feet to a point on the centerline of said open ditch; thence S 03°41'24" W with said centerline, 95.31 feet to a point: thence S 89° 15' 11" E (passing through a 5/8 inch rebar set at the top of the bank of said open ditch at 12.55 feet and a 5/8 inch rebar set at 853.01 feet). 878.01 feet to a PK nail set on the east line of said Northeast; thence N 00°37'50" E with said east line (also the centerline of St. Marys Road - C.R. 41 A) (passing through a railroad spike found at the east 1/8 post of said Northeast quarter at 97.09 feet), 1476.49 feet to the PLACE OF BEGINNING containing 42.188 acre more or less and subject to all highways and other legal easements of record.

I hereby certify the accompanying map and survey which it represents to be correct to the best of my knowledge and belief. All rebar set and called for are topped with a plastic Peramark cap stamped: KUCK & MORRISEY L.S. 6470.

Date: 4/16/92

Richard D. Morrisey, L.S. 6470

RICHARD D. MORRISEY

6470

6470

6470

SURV.

Signature by a representative of the County Healt denotes compliance with Health Regulations. Signed: Date		Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat. Signed:Date
Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed:		Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements. Signed: Date
CONSULTING ENGINEERS & SURVEYORS LIMA, OHIO 45805 TELEPHONE 228-1735 - AREA CODE 419	County <u>A</u> Drawn by Checked by _	KRIDGE REALTY Co. ug/arro Twp. Salem Sec. 4 E RDM Scale /"= 200' Drwg. No rdm Date 4/15/92 [2] T (co