



DESCRIPTION

Being a parcel of land situate in the Northwest quarter of Section 4, T-5-S, R-7-E, Union Township, Auglaize County, Ohio and more particularly described as follows:

Commencing at a stone found in a monument box at the northwest corner of said Northwest quarter of said Section 4; thence S 01°30'00" W with the west line of said Northwest quarter, 985.00 feet to a 5/8 inch rebar found and the PLACE OF BEGINNING; thence S 01°16'42" W continuing with said west line of said Northwest quarter, 1456.15 feet to a concrete corner post found at the southwest corner of said Northwest quarter; thence N 89°50'28" E with the south line of said Northwest quarter, 879.44 feet to a 5/8 inch rebar set; thence N 01°30'00" E, 1453.85 feet to a 5/8 inch rebar found; thence N 90°00'00" W, 885.00 feet to the PLACE OF BEGINNING containing 29.458 acres more or less and subject to all legal easements of record.

Signature by a representative of the County Health Dept. denotes compliance with Health Regulations.
Signed: _____ Date _____

Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat.
Signed: _____ Date _____

Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed: _____
for political S. D. of: _____ Date _____

Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements.
Signed: _____ Date _____

KUCK and MORRISEY, INC.
CONSULTING ENGINEERS & SURVEYORS
LIMA, OHIO 45805
TELEPHONE 228-1735 - AREA CODE 419
2807 CHAPEL HILL DRIVE

Client Mr. Max McMichael
County Auglaize Twp. Union Sec. 4
Drawn by J RDM Scale 1"=300' Drwg. No. _____
Checked by rdm Date 11/26/91
Sheet 1 of 1
(T-5-S; R-7-E)