

Commencing at a one inch rebar found in a monument box at the southeast corner of said Northeast quarter of said Section 15; thence N 87° 41'45" W with the south line of said Northeast quarter (also the centerline of Hengstler Road), 567.00 feet to a PK nail found and the PLACE OF BEGINNING; thence continuing N 87° 41'45" W with said south line and centerline, 189.00 feet to a PK nail set; thence N $02^{\circ}30'00$ " E (passing through a 5/8 inch rebar set at 15.00 feet), 260.00 feet to a 5/8 inch rebar set; thence S 87° 41'45" E, 189.00 feet to a 5/8 inch rebar found; thence S $02^{\circ}30'00$ " W (passing through a 5/8 inch rebar found; thence S $02^{\circ}30'00$ " W (passing through a 5/8 inch rebar found at 245.00 feet), 260.00 feet to the PLACE OF BEGINNING containing 1.128 acres more or less and subject to all highway and other legal easements of record.

I hereby certify the accompanying map and survey which it represents to be correct to the best of my knowledge and belief. All rebar set and called for are topped with a plastic Peramark cap stamped: KUCK & MORRISEY L.S. 6470.

Date: 7/14/92 Richard D. Morrisey, L.S. 6470
Kuck and Morrisey, Inc.

Signature by a representative of the County Health Dept. denotes compliance with Health Regulations. Signed: Date		Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat. Signed: Date	
Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed:		Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements. Signed: Date	
KUCK and MORRISEY, INC. CONSULTING ENGINEERS & SURVEYORS LIMA, OHIO 45805 TELEPHONE 228-1735 · AREA CODE 419 2807 CHAPEL HILL DRIVE	County Ac Drawn by Checked by	Stoice PPT1	Twp. Daction Sec. 15 Scale Drwg. No. Date 7-14-92 (T-5-8; R-4-E)