\$00.10'50" E \$00.07'43"E N00°07'43"W, 320.94'	S 89° 53' 38" E S 89° 53' 38" E PARCEL 7.314 A N 89° 53' 38" W, N 89° 53' 38' 38' 38' 38' 38' 38' 38' 38' 38' 3	57,MS. 8M 2 57,MS. 8M 2 57,MS. 8M 2	56 Solver	SW 14  RICHA  MORI  MORI	
50,	PK nail fd. \$18" Robar fd. PK nail set  8 89° 58  @ Moulton-Ft. Amanda Rd	137" E, 1330	) <b>.</b> 63′		E. Line NW4 SW4Sec.3
\$ 89°49' 10" W, 8.50' \$ 00°09' 57"W, 19.42'	Monu Box @ SW Corner Sec. 23  are by a representative of the County of the County of the County of the Regulations.	Health Dept.	Signature by a rep Planning Commiss		SW4 Sec. 3
Signatudenote Signed	Monu Box @ SW Corner Sec. 23  are by a representative of the County of the County of the County of the Regulations.	Health Dept.  te ile limit juris- ng jurisdiction	Signature by a rep Planning Commiss Signed:  Signature by a redenotes that this p Signed:	resentative of the A	uglaize County Regional I of this platDate County Engineer's Dept. lat requirements Date

## DESCRIPTION PARCEL \* NO. 1

Being a parcel of land situate partially in the northwest quarter of the Southwest quarter of Section 33 and partially in the west three-fourth of the southwest quarter of the Northwest quarter of Section 33, T-4-S, R-5-E, Logar Township, Auglaize County, Ohio and more particularly described as follows:

BEGINNING at a monument box found at the west quarter post of said Section 33; thence S  $00^{\circ}10^{\circ}50^{\circ}$  E with the west line of the Southwest quarter of said Section 33, 313.50 feet to a 5/8 inch rebar found; thence S  $89^{\circ}49^{\circ}10^{\circ}$  W, 8.50 feet to a PK nail found on the centerline of Moulton – Ft. Amanda Road; thence S  $00^{\circ}09^{\circ}57$ " W with said centerline, 19.42 feet to a PK nail set; thence S 89°58'37" E (passing through a 5/8 inch rebar set at 30.00 feet), 1,330.63 feet to a 5/8 inch rebar set on the east line of the northwest quarter of the Southwest quarter of Section 33; thence N 00°02'26" E with said east line, 331.04 feet to a 5/8 inch rebar set at the northeast corner of said northwest quarter of said Southwest quarter of said Section 33; thence N 89°53'38" W with the north line of said northwest quarter of said Southwest quarter, 330.83 feet to a 5/8 inch rebar set the southwest corner of the west three-fourth of the southwest quarter of the Northwest quarter of said Section 33; thence N 00°05'12" W with the east line of said west three-fourth, 149.91 feet to a 5/8 inch rebar set; thence N 89°53'38" W (passing through a 5/8 inch rebar set at 962.58 feet), 992.58 feet to a PK nail set on the west line of the Northwest quarter of said Section 33; thence S 00°07'43" E with said west line (also the centerline of Moulton- Ft. Amanda Road), 149.91 feet to the PLACE OF BEGINNING containing 13.500 acres more or less (of which 10.084 acres lies in the northwest quarter of the Southwest quarter and 3.416 acres lies in west three-fourth of the southwest quarter of the Northwest quarter of said Section 33) and subject to all highways and other legal easements of record.

## DESCRIPTION PARCEL & No. 2

Being a parcel of land situate in the west three-fourth of the southwest quarter of the Northwest quarter of Section 33, T-4-5, R-5-E, Logan Township, Auglaize County, Ohio and more particularly described as follows:

Commencing at a monument box found at the west quarter post of said Section 33; thence N Ø0°07'43" W with the west line of said Northwest quarter (also the centerline of Moulton - Ft. Amanda Rd.), 149.91 feet to a PK nail set and the PLACE OF BEGINNING thence continuing N Ø0°07'43" W with said west line and centerline, 320.94 feet to a PK nail set; thence S 89°53'38" E (passing through a 5/8 inch rebar set at 30.00 feet), 992.82 feet to a 5/8 inch rebar set on the east line of the west three-fourth of the southwest quarter of said Northwest quarter; thence S Ø0°05'12" E with said east line, 320.94 feet to a 5/8 inch rebar set; thence N 89°53'38" W (passing through a 5/8 inch rebar set; thence N 89°53'38" W (passing through a 5/8 inch rebar set at 962.58 feet), 992.58 feet to the PLACE OF BEGINNING containing 7.314 acres more or less and subject to all highways and other legal easements of record.

Signature by a representative of the County denotes compliance with Health Regulations.  Signed:  I		Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat.  Signed: Date		
Signature by a representative of City with 3 diction or Twp. Trustees or Village with zon denotes approval of this plat. Signed:I	ing jurisdiction	Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements.  Signed: Date		
KUCK AND MORRISEY, INC.  CONSULTING ENGINEERS & SURVEYORS  2807 CHAPEL HILL DRIVE  LIMA, OHIO 45805 - 228-1735	Checked by	KRIDGE REALTY Company USIOLER Twp. Logan Sec. 33 PROM Scale Drwg. No rdm Date 11/12/93 of 2 (T-4-S:R-5-E)		