



LEGEND:  
 °a ~ 5/8" Rebar set during previous survey.  
 °b ~ RR spike found  
 °c ~ Iron Pipe found  
 °d ~ PK nail found

Scale: 1" = 200'

#### DESCRIPTION

Being a parcel of land situate in the north half of the Northwest quarter of Section 25, T-5-S, R-5-E, Moulton Township, Auglaize County, Ohio and more particularly described as follows:

BEGINNING at a railroad spike found at the intersection of the center line of Glynwood Road and the west line of the said Northwest quarter of said Section 25; thence N 00° 40' 00" E with said west line of said Northwest quarter of said Section 25, 230.00 feet to a 5/8 inch rebar found; thence S 85° 15' 51" E, 371.34 feet to a 5/8 inch rebar found; thence S 01° 00' 00" W, 230.00 feet to a PK nail found on the center line of Glynwood Road; thence N 85° 15' 00" W with said center line, 370.00 feet to the PLACE OF BEGINNING containing 1.953 acres more or less and subject to all highway and other legal easements of record.



Signature by a representative of the County Health Dept. denotes compliance with Health Regulations.  
 Signed: \_\_\_\_\_ Date \_\_\_\_\_

Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat.  
 Signed: \_\_\_\_\_ Date \_\_\_\_\_

Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed: \_\_\_\_\_  
 for political S. D. of: \_\_\_\_\_ Date \_\_\_\_\_

Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements.  
 Signed: \_\_\_\_\_ Date \_\_\_\_\_

#### KUCK and MORRISEY, INC.

CONSULTING ENGINEERS & SURVEYORS  
 LIMA, OHIO 45805  
 TELEPHONE 228-1735 - AREA CODE 419  
 2807 CHAPEL HILL DRIVE

Client Monterey Enterprises, Inc.  
 County Auglaize Twp. Moulton Sec. 25  
 Drawn by RDM Scale \_\_\_\_\_ Drwg. No. \_\_\_\_\_  
 Checked by rdm Date 2/5/92  
 Sheet 1 of 1  
 (T-5-S; R-5-E)

5-464