



PLAT OF A SURVEY
IN THE SOUTHEAST 1/4
OF SECTION 2, T7S-R4E,
GERMAN TOWNSHIP,
AUGLAIZE COUNTY, OHIO



Scale: _____



James D. Sheldon
Reg. Surveyor #4569



LEGEND

- - I.P. SET
- - I.P. FOUND
- ⊙ - P.K. NAIL

Signature by a representative of the County Health Dept. denotes compliance with Health Regulations. Signed: _____ Date _____		Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat. Signed: _____ Date _____	
Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed: _____ for political S.D. of: _____ Date _____		Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements. Signed: _____ Date _____	
Sheldon & Assoc., Inc. 1280 N. Cole St. Lima, Ohio 45801		Client <u>Red Kuck Real Estate</u> County <u>Auglaize</u> Twp. <u>German</u> Sec. <u>2</u> Drawn by <u>D.K.</u> Scale _____ Drwg. No. <u>14,965-D</u> Checked by _____ Date <u>9/16/91</u> Sheet <u>1</u> of <u>2</u> <u>J-737</u> (T <u>7</u> S; R <u>4</u> E)	

DESCRIPTION
JOB #14,965-D



Scale: _____

Being a parcel of land situated in German Township, Auglaize County, Ohio in the southeast $\frac{1}{4}$ of Section 2, Township 7 South, Range 4 East and being more particularly described as follows:

Commencing for reference at a P.K. nail found marking the southwest corner of the south $\frac{1}{2}$ of the southeast $\frac{1}{4}$ of Section 2 and the centerline of Lock Two Road (C-70) -

Thence east, on and along said centerline, for a distance of 280.00 feet to a P.K. nail found -

Thence north, for a distance of 120.00 feet to an iron pipe found marking the principal point of beginning for the parcel to be conveyed by this instrument -

Thence north, for a distance of 20.00 feet to a $\frac{5}{8}$ inch iron pin set -

Thence east, for a distance of 80.00 feet to an iron pin found -

Thence south, for a distance of 20.00 feet an iron pin found -

Thence west, for a distance of 80.00 feet to the point of beginning.

Containing 0.0037 acres of land, subject, however to all legal easements and rights-of-way.

Note: All bearings refer to the centerline of Lock Two Road (C-70) as being east.


James D. Sheldon
Reg. Surveyor #4569

Signature by a representative of the County Health Dept. denotes compliance with Health Regulations.

Signed: _____ Date _____

Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat.

Signed: _____ Date _____

Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed: _____

for political S.D. of: _____ Date _____

Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements.

Signed: _____ Date _____

Sheldon & Assoc., Inc.
1280 N. Cole St.
Lima, Ohio 45801

Client Red Kuck Real Estate
County Auglaize Twp. German Sec. 2
Drawn by _____ Scale _____ Drwg. No. 14,965-D
Checked by _____ Date 9/17/91
Sheet 2 of 2 J-738 (T 7 S 4 E)