


LEGEND

- "A" = CORNER STONE AT N.E. COR. ~ SECTION 10.
- "B" = CORNER STONE AT N.W. COR. ~ N.E. 1/4 ~ SECTION 10.
- "C" = P.K. NAIL FOUND ON CENTERLINE RAILROAD RIGHT-OF-WAY.
- "D" = SET 5/8" IRON BAR
- "E" = RAILROAD SPIKE SET AT N.E. COR OF THIS SURVEYED TRACT. (FOUND R.R. SPK. BY STIMMEL 042' NORTH)
- "F" = FOUND IRON PIPE SET BY STIMMEL SURVEY.
- "G" = 5/8" X 30" IRON BAR SET.


LOCATION SKETCH



SECTION 10

NOTES

- (1) THIS IS A RETRACING OF A SURVEY BY CLAYTON STIMMEL DATED DEC. 7, 1966.
- (2) THE EAST RAILROAD R/W LINE AS DETERMINED BY STIMMEL IS EAST OF THIS SURVEYOR'S DETERMINATION BY 0.17' AT THE SOUTH END AND 0.14' AT THE NORTH END OF THIS SURVEYED TRACT. THIS RETRACING OF STIMMEL'S SURVEY ACCEPTS HIS DETERMINATION.



SURVEYED BY Gordon L. Geeslin
GORDON L. GEESLIN
REGISTERED SURVEYOR
NR 5372


DOENGES SURVEY

PART OF THE N.W. 1/4 OF THE N.E. 1/4 OF SECTION 10,
TOWN 7 SOUTH, RANGE 4 EAST (GERMAN TWP.),
AUGLAIZE COUNTY, OHIO.

SEPTEMBER 15, 1989

SCALE 1"=100'

GORDON L. GEESLIN
LAND SURVEYOR
810 EAST MARKET STREET
CELINA, OHIO J-749
PHONE (419) 586-6155



PERMANENT PARCEL No. _____		
Part of: _____ Sec. _____ T. _____ R. _____ Township		
Grantor: _____ Area Retained: _____ Acres		
Grantee: _____ Area Transferred: _____ Acres		
Deed References: _____		
APPROVALS:	Board of Health	County Sanitary Engineer
AGENCY:	County Engineer	
DATE:		