

- LEGEND:**
- _a ~ PK nail found
 - _b ~ Capped 5/8" rebar, fd.
 - _c ~ Capped 5/8" rebar set
 - _d ~ PK nail and shinner set
 - _e ~ 8" Ø wood corner post, fd.



I hereby certify the accompanying map and survey which it represents to be correct to the best of my knowledge and belief. All rebar set and called for are topped with a plastic Perumark cap stamped:

KUCK & MORRISEY L.S. 6470

Date: 3/18/00

Richard D. Morrissey, L.S. 6470
KUCK and MORRISEY, Inc.

DESCRIPTION

Being a parcel of land situate in the northwest quarter of the Southwest quarter of Section 3, T-5-S, R-7-E, Union Township, Auglaize County, Ohio and more particularly described as follows:

BEGINNING at a monument box found at the northeast corner of said northwest quarter of said Southwest quarter; thence S 00°38'24" W with the east line of said northwest quarter of said Southwest quarter (also the centerline of Boundary Road), 216.70 feet to a PK nail found; thence N 89°21'36" W (passing through a capped 5/8 inch rebar found at 23.00 feet), 232.42 feet to a capped 5/8 inch rebar from a previous survey; thence S 00°38'24" W (passing through a 5/8 inch rebar found at 208.00 feet), 395.42 feet to a capped 5/8 inch rebar set; thence S 89°21'36" E (passing through a capped 5/8 inch rebar set at 209.42 feet), 232.42 feet to a PK nail and shinner set of the east line of said northwest quarter of said Southwest quarter; thence S 00°38'24" W with said east line (also the centerline of Boundary Road), 709.82 feet to a PK nail and shinner set at the southeast corner of said northwest quarter of said Southwest quarter; thence N 83°12'13" W with the south line of said northwest quarter of said Southwest quarter (passing through a capped 5/8 inch rebar set at 23.13 feet), 1,370.16 feet to a 8" diameter wood corner post found at the southwest corner of said northwest quarter of said Southwest quarter; thence N 00°51'18" E with the west line of said northwest quarter of said Southwest quarter, 1,329.95 feet to a capped 5/8 inch rebar set at the northwest corner of said northwest quarter of said Southwest quarter; thence S 82°50'51" E with the north line of said northwest quarter of said Southwest quarter (passing through a capped 5/8 inch rebar set at 1,342.93 feet), 1,366.08 feet to the PLACE OF BEGINNING containing 39.289 acres more or less and subject to all highway and other legal easements of record.

Signature by a representative of the County Health Dept. denotes compliance with Health Regulations.
Signed: _____ Date: _____

Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat.
Signed: _____ Date: _____

Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed: _____
for political S. D. of: _____ Date: _____

Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements.
Signed: _____ Date: _____

KUCK AND MORRISEY, INC.
CONSULTING ENGINEERS & SURVEYORS
2807 CHAPEL HILL DRIVE
LIMA, OHIO 45805 - 228-1735

L-188

Client Madeline FUNK % Oakridge Realty Co
County Auglaize Twp. Union Sec. 3
Drawn by RDM Scale 1"=300' Drwg. No. _____
Checked by rdm Date 3/18/00
Sheet 1 of 1
(T-5-S; R-7-E)

