

S.W. COR.-
SEC. 4

W. LINE - S.W. 1/4 - SEC. 4

S 00°52'02" W 2637.26'

STATE ROUTE 364

W. 1/4 PT.
SEC. 4

972.81'

36.23'

S 00°18'17" E

6.69'

33.32'

36.57'

I. PIPE FD. IS N. 89°27'58" WEST -
1.74' FROM CALC. COR. (DIST.'S ARE TO COR.)

S 89°27'58" W

143.28'

38.78'

64.49'

RIGHT-OF-WAY LINE

0.930 TOTAL ACRES

S 80°08'18" E
189.59'

S 00°52'02" W

S 00°52'02" W

46.60'

77.57'

N 89°07'57" W
5.00'

CONC. MON. FD. IS N. 87°40'46" WEST -
1.75' FROM CALC. COR. (DIST.'S ARE TO COR.)

N 87°40'46" W 325.60'

LEGEND

- ⊕ = IRON PIPE FOUND.
- ⊙ = P.K. NAIL FOUND.
- ⊙ = CONCRETE MONUMENT FOUND.
- ⊙ = 5/8 INCH IRON BAR FOUND.
- ⊙ = 5/8 INCH IRON BAR SET.

SURVEYED BY


James W. Geeslin
JAMES W. GEESLIN
P.S. No. 7764

MANNING SURVEY

PART OF THE S.W. 1/4 OF SECTION 4, TOWN 6 SOUTH, RANGE 4
EAST, (ST. MARYS TOWNSHIP), AUGLAIZE COUNTY, OHIO.

SEPTEMBER 15, 2000

SCALE 1" = 50'



GEESLIN
LAND SURVEYING

804 EAST MARKET STREET
P.O. BOX 422
CELINA, OHIO 45822
PHONE: (419) 586-6155
FAX: (419) 586-1826

m-320

PERMANENT PARCEL No.	Part of	Sec.	T.	R.	Acres Disturbed	Acres Area Retained	Township
	Grantor						
	Grantee						
	Used References						
APPROVALS AGENCY	DATE	Survey of Health	County Engineer				