


SURVEYOR'S CERTIFICATION

This is to certify to the Chicago Title Insurance Company and to Bank One Columbus, N.A. that this drawing represents a true and accurate survey made by Gordon L. Geeslin, Registered Surveyor number 5372 on January 15, 1992; that the improvements located on this property do not encroach onto any adjoining property nor do any improvements located on any adjoining property encroach onto this property, except as noted, and that the west right-of-way line of State Route 198 and the north right-of-way line of Hamilton Street are contiguous to the perimeter lines of the surveyed property as shown.

Certified this 15th day of January 1992.

Gordon L. Geeslin
Gordon L. Geeslin
Registered Surveyor 5372



LEGEND

- "A" = RAILROAD SPIKE CALLED FOR ON PLAT OF GRAND VIEW ESTATES No. 2.
"B" = 5/8" IRON BAR FOUND 0.06' S. OF & 0.32' W. OF LOT COR.
"C" = 5/8" IRON BAR FOUND 0.03' N. OF & 0.19' W. OF INTERSECTION OF PROPERTY LINES EXTENDED.
"D" = "P.K." NAIL SET.
"E" = 5/8" X 30" IRON BAR SET.
"F" = POWER POLE ON PROPERTY CORNER.
CURB AND OR CURB & GUTTER OR LINE OF SIDEWALK = - - - - -

NOTES


THE SIDEWALK IS BUILT OVER THE PROPERTY LINE AS SHOWN.

THIS PROPERTY IS NOT IN A FLOOD HAZARD AREA.

DIAMOND SAVINGS & LOAN CO. SURVEY
OF LOT No. 65 OF GRAND VIEW ESTATES
No. 1 IN THE CITY OF WAPAKONETA, AUG-
LAIZE COUNTY, OHIO.
JANUARY 15, 1992 SCALE 1" = 30'

GORDON L. GEESLIN

LAND SURVEYOR
810 EAST MARKET STREET
CELINA, OHIO
PHONE (419) 586-6155



PERMANENT
PARCEL No. _____

Part of: _____ Sec. _____ T _____ R _____ Township
Grantor: _____ Area Retained: _____ Acres
Grantee: _____ Area Transferred: _____ Acres
Deed References: _____

APPROVALS

AGENCY
DATE

Board of Health

County Sanitary Engineer

County Engineer

M 602