THE Corner W E' SW 1/4 S	0ec. 4
ESR 703 2.	
50.00' Egress Esm 4.26'	Scale: //= 200,
150 150 150° E	
N 89°15'0 50'Ing 00° 45'0	
200	15'00"W, 665.20' - B
P.O.B. Parcel	2
N89°15'.00"E, 7 321.40'	
Parcal 1	LEGEND
M: 00 PARCEL 1 00:55 P. 19.	PARCEL 2 9 9 B~ 1" Iron
7.648 Acres (2) 19	257 Acres & Pipe (fd)
N	O"W,
	0,000
A CNOCKE SO	W 00 N
870.00 /2.	
A North Carolling Solling Soll	
N-67	S. Line SW14 Sec.4 SE Corner SW14 Sec.4 SW14 Sec.4
Signature by a representative of the County Health Dept. denotes compliance with Health Regulations. Signed: Date	Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat. Signed:
Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed:	Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements. Signed: Date
KUCK and MORRISEY, INC. CONSULTING ENGINEERS & SURVEYORS LIMA, OHIO 45805 TELEPHONE 228-1735 - AREA CODE 419 2807 CHAPEL HILL DRIVE Client 703 County A: County A: Checked by Sheet /	<u> </u>
THE REPORT OF THE PARTY OF THE	$(T-\cancel{G}-S;R-\cancel{Q}-E)$

PARCEL 2 DESCRIPTION

Being a parcel of land situate in the east half of the east half of the Southwest quarter of Section 4, T-6-6, R-4-E, St. Marys Township, Auglatze County, Ohio and more particularly described as follows:

Commencing at the northwest corner of said east half of said east half of said Southwest quarter; thence S 00°45'00" E with the west line of said east half of said east half of said Southwest quarter (crossing the centerline of State Route 703 at 599.00 feet), 1344.00 feet to a point and the PLACE OF BEGINNING thence continuing S 00°45'00" E with said west line of said east half of said east half of said Southwest quarter, 1132.96 feet to a 5/8 inch rebar found on the north right-of-way line of the Norfolk and Western Railroad; thence S 61°49'00" E with said north right-of-way line of said Norfolk and Western Railroad, 363.34 feet to a 5/8 inch rebar found on the south line of the Southwest quarter of said Section 4; thence N 89°13'27" E with said south line, 341.50 feet to a 5/8 inch rebar found at the southeast corner of said Southwest quarter of said Section 4; thence N 80°30'20" W with the east line of said Southwest quarter, 1308.60 feet to a one inch iron pipe found; thence S 89°15'00" W, 665.20 feet to the PLACE OF BEGINNING containing 19.257 acres more or less and subject to all legal easements of record.

A REAL TRANSPORT SECTION CONTRACTOR DESCRIPTION OF THE PARTY OF THE PA	1	-	0	G
	Senso Contractor	NAMES AND ADDRESS OF	Name (SA)	

Signature by a representative of the County Health Dept. denotes compliance with Health Regulations. Signed: Date	Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat. Signed:Date	
Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed:	Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements. Signed: Date	
CONSULTING ENGINEERS & SURVEYORS LIMA, OHIO 45805 Checked I	703 Limited Partnership Auglaina Twp. 54. Marya Sec. 4 Uprod Scale 1 200 Drwg. No. Dy 15/0 Date 11/28/91 (T-6-S; R-4-E)	