

GORDON L. GEESLIN

REGISTERED LAND SURVEYOR

PHONE 419-586-6155

September 20, 1991

Bertke Survey Description

Being a parcel of land situated in St. Marys Township, Auglaize County, Ohio, in the southwest quarter of Section 34, Township 6 South, Range 4 East. Being more particularly described as follows:

Commencing for reference at an iron bar in a monument box at the southwest corner of said Section 34-

Thence, east, along the south line of the southwest quarter of said Section 34 and the centerline of Montezuma Road, a distance of sixty-eight and 78/100 (68.78) feet to a mine spike. Said point being the place of beginning for the parcel to be conveyed by this instrument-

Thence, continuing, east, along the last described line, a distance of two hundred two (202.00) feet to a mine spike-

Thence, north, a distance of two hundred thirty-seven and 39/100 (237.39) feet to a 5/8 inch iron bar-

Thence, west, a distance of two hundred fifty-five and 75/100 (255.75) feet to a mine spike in the center of County Road 66-A-

Thence, south $12^{\circ}45'27"$ east, along the centerline of said County Road 66-A, a distance of two hundred forty-three and 40/100 (243.40) feet to the place of beginning.

Containing 1.247 acres of land more or less of which 0.247 is road right-of-way.

Subject to all easements and right-of-way of record.

Reference is made to a survey of this area by Gordon L. Geeslin, Registered Surveyor 5372, dated September 20, 1991.

Surveyed by

Gordon L. Geeslin

Registered Surveyor 5372

GORDON L.

GESLIN

STERNON

PV E VOLUMENTARIO

N-275

810 EAST MARKET STREET

CELINA, OHIO 45822