

N-708

÷,

## KENT B. MARBAUGH

## REGISTERED LAND SURVEYOR

1210 Yorkshire Court Celina, Ohio 45822 PHONE 419-586-4293

April 20, 2000

## HUMANE SOCIETY SURVEY DESCRIPTION

Being a parcel of land situated in Moulton Township, Auglaize County, Ohio, and in the northeast quarter of Section 26, Township 5 South, Range 5 East, being more particularly described as follows:

Commencing at a steel cornerpost at the center of said Section 26;

thence N 00° 27' 49" E, 1328.93 feet along the west line of the northeast quarter of said Section 26 to an iron pin with cap set as the Point of Beginning;

thence continuing  $N 00^{\circ} 27' 49'' E$ , 656.96 feet along the last described line and passing through an iron pin with cap set at 636.96 feet to a MAG nail set;

thence N 65° 39' 12" E, 427.45 feet along the centerline of Glynwood Road to a MAG nail set;

thence S 00° 27' 49" W, 336.33 feet and passing through an iron pin with cap set at 20.00 feet to an iron pin with cap set;

thence S 89° 32' 11" E, 261.33 feet and passing through an iron pin with cap set at 208.12 feet to a point in the center of the Auglaize River;

thence S 17° 28' 51" E, 148.28 feet along the centerline of the Auglaize River to a point; thence S 23° 10' 40" E, 113.24 feet along the centerline of the Auglaize River to a point; thence S 30° 44' 40" E, 133.92 feet along the centerline of the Auglaize River to a point; thence S 29° 49' 22" E, 162.88 feet along the centerline of the Auglaize River to a point;

thence N 89° 32' 11" W, 891.96 feet and passing through an iron pin with cap set at 78.44 feet to the Point of Beginning, containing 10.869 acres of land more or less, subject to all valid easements and right-of-way.

All bearings were calculated from angles turned in an actual field survey by Kent B. Marbaugh, Registered Surveyor #7421, dated April 13, 2000, on file in the County Engineer's Office.

N-709

Surveyed by <u>Host Mailaud</u> Kent B Marbaugh P.S. #7421