

Being a parcel of land situate in the southeast quarter of the Northeast quarter of Section 29, T-4-S, R-4-E, Salem Township, Auglaize County, Ohio and more particularly described as follows:


Commencing at a stone found in a monument box found at the northeast corner of said Northeast quarter of said Section 29; thence S 00°03'01" W (basis of bearing) with the east line of said northeast quarter of said Northeast quarter, 1,326.40 feet to a PK nail and shiner set at the southeast corner of said northeast quarter of said Northeast quarter (reference ODOT centerline monument S 00°14'38" W, 12.74 feet of the PK nail and shiner set); thence N 89°46'52" W with the north line of said southeast quarter of said Northeast quarter, 172.42 feet to a PK nail and shiner set and the **PLACE OF BEGINNING** thence continuing N 89°46'52" W with said north line of said southeast quarter of said Northeast quarter, 1,156.95 feet to a capped 5/8 inch rebar set at the northwest corner of said southeast quarter of said Northeast quarter (reference ODOT centerline monument S 47°35'56" E, 29.52 feet of the capped 5/8 inch rebar set); thence S 00°11'56" W with the west line of said southeast quarter of said Northeast quarter, 996.48 feet to a capped 5/8 inch rebar set; thence S 89°45'44" E (passing through a 6" diameter wood post found at 45.07 feet), 1,328.59 feet to a 6" diameter wood post found on the east line of said southeast quarter of said Northeast quarter; thence N 00°14'38" E with said east line, 748.80 feet to the east edge of a 10" square concrete post found; thence S 87°43'55" W (passing through a 10" square concrete post found at 104.08 feet), 173.11 feet to a capped 5/8 inch rebar set; thence N 00°14'38" E (passing through a capped 5/8 inch rebar set at 225.63 feet), 255.63 feet to the **PLACE OF BEGINNING** containing 29.408 acres more or less and subject to all highways and other legal easements of record.

Surveyed by: **KUCK and MORRISEY, Inc.** Richard D. Morrissey, L.S. No. 6470 (Ohio)

I hereby certify the accompanying map and survey which it represents to be correct to the best of my knowledge and belief. All rebar set and called for are topped with a plastic Peramark cap stamped:
KUCK & MORRISEY, L.S. 6470

Date: 1/23/03

Richard D. Morrissey, L.S. 6470
KUCK and MORRISEY, Inc.



Signature by a representative of the County Health Dept. denotes compliance with Health Regulations.
Signed: _____ Date: _____

Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat.
Signed: _____ Date: _____

Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed: _____ Date: _____
for political S. D. of: _____

Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements.
Signed: _____ Date: _____

KUCK AND MORRISEY, INC.
CONSULTING ENGINEERS & SURVEYORS
2807 CHAPEL HILL DRIVE
LIMA, OHIO 45805 - 228-1735

Client Eugene BALTHASER % Joe Mack
County Auglaize Twp. Salem Sec. 29
Drawn by SRDM Scale 1" = 400' Drwg. No. _____
Checked by rdm Date 1/23/03
Sheet 1 of 1 0-96 (T-4-S; R-4-E)