

May 24, 2002

## STROH SURVEY DESCRIPTION

Being a parcel of land situated in St. Marys Township, Auglaize County, Ohio, in the northwest quarter of Section 12, Township 6 South, Range 4 East. Being more particularly described as follows:

Commencing for reference at the cornerstone at the southwest corner of the northwest quarter of said Section 12 -

Thence, North 89°15'30" East, along the south line of the northwest quarter of said Section 12, a distance of 220.00 feet to an iron pipe -

Thence, North, a distance of 20.00 feet to a point. Said point being the place of beginning for the parcel of land to be conveyed by this instrument -

Thence, North 89°15'30" East, a distance of 22.00 feet to a 5/8 inch iron bar -

Thence, North, a distance of 180.00 feet to a 5/8 inch iron bar -

Thence, South 89°15'30" west, a distance of 22.00 feet to an iron pipe -

Thence, South, a distance of 180.00 feet to the place of beginning.

Containing 0.091 acre of land more or less.

Subject to all easements and right-of-way of record.

Reference is made to a survey of this area by James W. Geeslin, Professional Surveyor 7764, dated May 24, 2002. On file in the County Engineer's Office.

Surveyed by

James W. Geeslin

Professional Surveyor 7764

GEESLIN LAND STRVEYING

> P.O. BOX 422 CELINA, OHIO 45822

PHONE: (419) 586-6155 FAX: (419) 678-9332

Granton Area Retained Acres
Grantee Area Retained Acres
Deed References

Boner .