D MB C& TR230	S89°46'30"E PLACE OF 1,285.89'- N BEGINNING N			
MB (& TR230 (Valine Rd)	20.00' 20.75' Scale:			
0	PARCEL Nº 1 40.000 Acres 120.1381			
214 Soc. 6,	W N89°46'30"W 1,292.06' 1,			
(N/S Ha	N°00 N PARCEL Nº2 42.943 Acres N°00, N°00, N°00, N°00,			
E/W Half Sec. Line	S88°57'46"W 54.41 E S (J20' (CSRIIG SPLACE OF			
NO2°12'14"W,	1 588°57'46"W H BEGINNING "2			
LEGEND:  C - Stone found previous survey at W 1/4 post Section 20 D - Iron pin found in monument box at N 1/4 post Section 20 E - East 1/4 post of Section 20 as calculated in previous survey G - 10" square concrete post found at the S 1/4 post Section 20 H - monument box at the intersection of the centerline of State Route 116 and the east line of the Southeast quarter of said Section 20 I - PK nail and shiner set J - Capped 5/8 inch rebar set K - 7" diameter steel post found - used for alignment of west line L - 5/8 inch rebar found adjacent to north side 7" diameter steel post M - railroad spike found N - Iron pin found at northeast corner of Section 20 O - 4" square concrete post found				
I hereby certify the accompanying map and survey, which it represents to be correct to best of my knowledge and belief. All rebar set and called for are topped with a plastic Peramark cap stamped:  KUCK & MORRISEY LS. 6470  Richard D. Morrisey, L.S. 6470 (Ohio)  KUCK & MORRISEY, Inc.				
Signature by a representative of the County Healt denotes compliance with Health Regulations.  Signed: Date	Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat.  Signed:Date			
Signature by a representative of City with 3 mile lindiction or Twp. Trustees or Village with zoning juridenotes approval of this plat. Signed:	isdiction signature by a representative of the County Engineer's Dept.			
CONSULTING ENGINEERS & SURVEYORS  2807 CHAPEL HILL DRIVE  LIMA, OHIO 45805 228-1735	Client Mr. Joe MACK  County Auniatze Twp. Salem Sec. 20  Drawn by RDM Scale 1"=600' Drwg. No.  Checked by rdm Date 11/27/06  Sheet of 2 (T-4-S; R-4-E)			

P-475

## **DESCRIPTION - PARCEL No. 1**

Being a parcel of land situate in the east half of the Northeast quarter of Section 20, T-4-S, R-4-E, Salem Township, Auglaize County, Ohio and more particularly described as follows:

BEGINNING at a iron pin found at the northeast corner of said Northeast quarter; thence S 00°02'16" W with the east line of said Northeast quarter (passing through a 4" square concrete post found at 20.75 feet), 1,351.78 feet to a capped 5/8 inch rebar set; thence N 89°46'30" W, 1,292.06 feet to a capped 5/8 inch rebar set; thence N 00°17'56" E (passing through a 5/8 rebar found at 1,331.78 feet (adjacent to the north side of a 7" diameter steel post)), 1.351.78 feet to a railroad spike found on the north line of said Northeast quarter; thence S 89°46'30" E with said north line (also the centerline of T.R. 230 (Valine Road)), 1,285.89 feet to the PLACE OF BEGINNING containing 40.000 acres more or less and subject to all highway and other legal easements of record. Surveyed by: KUCK and MORRISEY, Inc., Richard D. Morrisey, L.S. No. 6470 (Ohio)

## **DESCRIPTION - PARCEL No. 2**

Being a parcel of land situate in the east half of the Northeast quarter and the Southeast quarter of Section 20, T-4-S, R-4-E, Salem Township, Auglaize County, Ohio and more particularly described as follows:

BEGINNING at an iron pin found in a monument box at the intersection of the centerline of State Route 116 and the east line of the Southeast quarter of said Section 20; thence \$88°57'46" W with said centerline of said State Route 116, 1,235.69 feet to a PK nail and shiner set; thence N 02°12'14" W (passing through a capped 5/8 inch rebar set at 20.00 feet), 196.00 feet to a capped 5/8 inch rebar set (reference 3 1/2" steel post found \$11°10'15" E, 0.92 feet); thence \$88°57'46" W, 54.41 feet to a 5" diameter steel post found; thence N 00°17'56" E, 1,271.25 feet to a capped 5/8 inch rebar set; thence \$89°46'30" E, 1,292.06 feet to a capped 5/8 inch rebar set on the east line of said Northeast quarter of said Section 20; thence \$00°02'16" W with said east line of said Northeast quarter, 1,302.15 feet to the calculated southeast corner of said Northeast quarter as calculated during a previous survey; thence \$00°10'00" W with the east line of said Southeast quarter of said Section 20, 136.51 feet to the PLACE OF BEGINNING containing 42.943 acres more or less and subject to all highway and other legal easements of record.

Surveyed by: KUCK and MORRISEY, Inc., Richard D. Morrisey, L.S. No. 6470 (Ohio)

I hereby certify the accompanying map and survey, which it represents to be correct to best of my knowledge and belief. All rebar set and called

Richard D. Merrisey, L.S. 6470 (Ohio) KUCK & MORRISEY, Inc.

for are topped with a plastic Peramark cap stamped:

KUCK & MORRISEY 1.S. 6470

	The state of the s		
Signature by a representative of the County Health Dept. denotes compliance with Health Regulations.  Signed: Date	Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat.  Signed:Date		
Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed:	Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements.  Signed: Date		
101 A Ma	TOR MACK		

## **KUCK AND MORRISEY, INC.**

CONSULTING ENGINEERS & SURVEYORS
2807 CHAPEL HILL DRIVE
LIMA, OHIO 45805 - 228-1735

Client Mr. Joe M.	ACK		
County <u>Avalaize</u>		Salem	Sec
Drawn by RDM	Scale_	1"= 600	_Drwg. No
Checked by		Date	Sec
Sheetof			(T-4-S; R-4-E