

DESCRIPTION

Being a parcel of land situate in the Southwest quarter of Section 1, T-5-S, R-7-E, Union Township, Auglaize County, Ohio and more particularly described as follows:

BEGINNING at a drilled hole found in the lid of a monument box at the southwest corner of said Southwest quarter; thence N 01°05'54" E (basis of bearing – previous survey) with the west line of said Southwest quarter (also the centerline of Valley Graham Road), 654.82 feet to a PK nail and shiner set; thence S 89°11'21" E (passing through a capped 5/8 inch rebar set at 25.00 feet), 332.70 feet to a capped 5/8 inch rebar set; thence S 01°06'45" W (passing through a capped5/8 inch rebar found at 629.82 feet), 654.82 feet to a PK nail and shiner found on the south line of said Southwest quarter; thence N 89°11'21" W with said south line (also the centerline of Buckland-Holden Road), 332.54 feet to the PLACE F BEGINNING containing 5.000 acres more or less and subject to all highway and other legal easements of record.

I hereby certify the accompanying map and survey, which it represents to be correct to best of my knowledge and belief. All rebar set and called for are topped with a plastic Peramark cap stamped:

KUCK & MORRISEY L.S. 6470

Date: 1/27/07

Richard D. Morrisey, L.S. 6470 (Ohio) KUCK & MORRISEY, Inc.



Signature by a representative of the County Health Dept. denotes compliance with Health Regulations. Signed: Date	Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat. Signed: Date
Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed: Date	Signature by a representative of the County Engineer's Dept.denotes that this plat meets tax map plat requirements. Signed: Date
KLICK AND MORRISEY INC. Client _K	eith A. & Tamara DANNER

KUCK AND MORRISEY, INC.

2807 CHAPEL HILL DRIVE LIMA, OHIQ 45805 - 228-1735