


- LEGEND:**
- C - Chiseled "x" in lid of monument box found at northwest corner of the east half of the Southwest quarter of Section 1
 - D - Railroad spike found at the southwest corner of the northeast quarter of the Southwest quarter of Section 1
 - E - One inch diameter iron pin found in a monument box at southwest corner of the east half of the Southwest quarter of Section 1
 - F - Monument box found at southeast corner of the Southwest quarter of Section 1
 - G - Calculated east eighth post of the Southwest quarter of Section 1
 - H - Gin spindle found
 - I - PK nail and shiner set
 - J - Capped 5/8 inch rebar set
 - K - Capped 5/8 inch rebar found
 - L - 5/8 inch rebar found
 - M - Capped 5/8 inch rebar set adjacent to four inch wood corner post
 - N - Two inch diameter steel corner post found

I hereby certify the accompanying map and survey, which it represents to be correct to best of my knowledge and belief. All rebar set and called for are topped with a plastic Peramark cap stamped:
KUCK & MORRISEY L.S. 6470
Date: 4/25/08
Richard D. Morrissey, L.S. 6470 (Ohio)
KUCK & MORRISEY, Inc.



KUCK AND MORRISEY, INC.
CONSULTING ENGINEERS & SURVEYORS
2807 CHAPEL HILL DRIVE
LIMA, OHIO 45805 - 228-1735

Client Nancy Carroll
County Auglaize Twp. Duchauquet Sec. 1
Drawn by J. RDM Scale 1"=150' Drwg. No.
Checked by Date 4/24/08
Sheet 1 of 3
(T-5-S; R-6-E)

DESCRIPTION - PARCEL No. 1

Being a parcel of land situate in the east half of the Southwest quarter of Section 1, T-5-S, R-6-E, Duchouquet Township, Auglaize County, Ohio and more particularly described as follows:

Commencing at a chiseled "x" in the lid of a monument box found at the northwest corner of said east half of said Southwest quarter; thence S 00°59'20" W (basis of bearing - previous survey) with the west line of said east half of said Southwest quarter (also the centerline of Mudsock Road), 854.13 feet (Deed call: 854.26 feet) to a gin spindle found and the **PLACE OF BEGINNING** thence continuing S 00°59'20" W with said west line and centerline, 293.00 feet to a PK nail and shiner set; thence S 89°22'53" E (passing through a capped 5/8 inch rebar set at 30.00 feet), 297.35 feet to a capped 5/8 inch rebar set; thence N 00°59'20" E, 293.06 feet to a capped 5/8 inch rebar set; thence N 89°23'35" W (passing through a 5/8 inch rebar found at 267.35 feet), 297.35 feet to the **PLACE OF BEGINNING** containing 2.000 acres more or less and subject to all highway and other legal easements of record. Road right-of-way occupies 0.202 acre. Deed reference: OR 525, Page 2259.

Surveyed by: **KUCK and MORRISEY, Inc.**, Richard D. Morrissey, L.S. No. 6470 (Ohio).

DESCRIPTION - PARCEL No. 2

Being a parcel of land situate in the east half of the Southwest quarter of Section 1, T-5-S, R-6-E, Duchouquet Township, Auglaize County, Ohio and more particularly described as follows:

Commencing at a chiseled "x" in the lid of a monument box found at the northwest corner of said east half of said Southwest quarter; thence S 00°59'20" W (basis of bearing - previous survey) with the west line of said east half of said Southwest quarter (also the centerline of Mudsock Road), 1,147.13 feet to a PK nail and shiner set and the **PLACE OF BEGINNING** thence S 89°22'53" E (passing through a capped 5/8 inch rebar set at 30.00 feet), 297.35 feet to a capped 5/8 inch rebar set; thence N 00°59'20" E, 293.06 feet to a capped 5/8 inch rebar set; thence S 89°12'59" E, 40.65 feet to a capped 5/8 inch rebar set; thence N 00°59'20" E, 197.00 feet to a capped 5/8 inch rebar found; thence S 89°23'35" E, 989.20 feet to a 5/8 inch rebar found on the east line of said Southwest quarter; thence S 01°01'13" W (passing the calculated east eighth post of said Southwest quarter at 651.99 feet), 914.65 feet to a capped 5/8 inch rebar set; thence N 89°37'21" W, 575.46 feet to a capped 5/8 inch rebar set adjacent to a four inch wood corner post found; thence N 00°13'37" W (crossing the east/west eighth line of said Southwest quarter at 262.66 feet), 265.88 feet to a two inch diameter steel corner post found; thence N 89°52'12" W, 745.68 feet to a railroad spike found at the southwest corner of the northeast quarter of said Southwest quarter; thence N 00°59'20" E with the west line of the east half of said Southwest quarter (also the centerline of Mudsock Road), 167.43 feet to the **PLACE OF BEGINNING** containing 19.874 acres more or less and subject to all highway and other legal easements of record. Road right-of-way occupies 0.115 acre.

Deed reference: OR 525, Page 2259.

Surveyed by: **KUCK and MORRISEY, Inc.**, Richard D. Morrissey, L.S. No. 6470 (Ohio).

I hereby certify the accompanying map and survey, which it represents to be correct to best of my knowledge and belief. All rebar set and called for are topped with a plastic Peramark cap stamped:
KUCK & MORRISEY, L.S. 6470

Date: 4/25/08

Richard D. Morrissey, L.S. 6470 (Ohio)
KUCK & MORRISEY, Inc.



Signature by a representative of the County Health Dept. denotes compliance with Health Regulations.
Signed: _____ Date: _____

Signature by a representative of the Auglaize County Regional Planning Commission denotes approval of this plat.
Signed: _____ Date: _____

Signature by a representative of City with 3 mile limit jurisdiction or Twp. Trustees or Village with zoning jurisdiction denotes approval of this plat. Signed: _____
for political S. D. of: _____ Date: _____

Signature by a representative of the County Engineer's Dept. denotes that this plat meets tax map plat requirements.
Signed: _____ Date: _____

KUCK AND MORRISEY, INC.
CONSULTING ENGINEERS & SURVEYORS
2807 CHAPEL HILL DRIVE
LIMA, OHIO 45805 - 228-1735

Client Nancy Carroll
County Auglaize Twp. Duchouquet Sec. 1
Drawn by J RDM Scale 1" = 80' Drwg. No. _____
Checked by rdm Date 4/24/08
Sheet 2 of 3
(T-5-S; R-6-E)