



#### DESCRIPTION - PARCEL No. 1

Being a parcel of land situate in the Southwest quarter of Section 21, T-5-S, R-5-E, Moulton Township, Auglaize County, Ohio and more particularly described as follows:

**BEGINNING** at a one inch iron pin found in a monument box at the northeast corner of said Southwest quarter; thence S 00°00'45" E (passing through a capped 5/8 inch rebar set at 25.00 feet), 882.45 feet to a capped 5/8 inch rebar set adjacent to the west side of a railroad tie corner post found; thence S 89°30'00" W (passing through a capped 5/8 inch rebar set at 2,619.54 feet), 2,644.54 feet to a PK nail and shiner set on the west line of said Southwest quarter of said Section 21; thence N 00°19'55" W with said west line (also the centerline of CR 91 (Moulton-Ft. Amanda Road)), 882.42 feet to a one inch iron pin found in a monument box found at the northwest corner of said Southwest quarter; thence N 89°30'00" E (basis of bearing - previous survey) with the north line of said Southwest quarter (also the centerline of CR 166 (Doering Road)), 2,649.46 feet to the **PLACE OF BEGINNING** containing 53.622 acres more or less and subject to all highway and other legal easements of record. Road right-of-way occupies 2.111 acres. Deed reference: O.R. 456, Page 1920. Part of Parcel No. G 2102100200.

Surveyed by: **KUCK and MORRISEY, Inc.**, Richard D. Morrissey, L.S. No. 6470 (Ohio).

I hereby certify the accompanying map and survey, which it represents to be correct to best of my knowledge and belief. All rebar set and called for are topped with a plastic Peramark cap stamped:  
**KUCK & MORRISEY L.S. 6470**

Date: 6/23/08

Richard D. Morrissey, L.S. 6470 (Ohio)  
**KUCK & MORRISEY, Inc.**



#### DESCRIPTION - PARCEL No. 2

Being a parcel of land situate in the West half of the Southeast quarter of Section 21, T-5-S, R-5-E, Moulton Township, Auglaize County, Ohio and more particularly described as follows:

Basis of bearing: north line of the Southwest quarter of said Section 21: N 89°30'00" E (previous survey)

**BEGINNING** at a one inch iron pin found in a monument box at the northwest corner of said Southeast quarter; thence N 89°30'35" E with the north line of said west half of said Southeast quarter (also the centerline of CR 166 (Doering Road)), 1,324.77 feet to a one inch iron pin found in a monument box found at the northeast corner of said west half of said Southeast quarter; thence S 00°07'39" W (passing through a capped 5/8 inch rebar set at 25.00 feet), 885.53 feet to a capped 5/8 inch rebar set adjacent to the south edge of a 10 inch diameter wood corner post found; thence S 89°38'32" W, 1,322.58 feet to a capped 5/8 inch rebar set adjacent to the west side of a railroad tie corner post found; thence N 00°00'45" W (passing through a capped 5/8 inch rebar set at 857.45 feet), 882.45 feet to the **PLACE OF BEGINNING** containing 26.861 acres more or less and subject to all highway and other legal easements of record. Road right-of-way occupies 0.760 acre. Deed reference: O.R. 456, Page 1920. Part of Parcel No. G 2102100200.

Surveyed by: **KUCK and MORRISEY, Inc.**, Richard D. Morrissey, L.S. No. 6470 (Ohio).

Mr. & Mrs. Frank RAHLE  
1367 Timberlane Dr.  
Lima, Ohio 45805

Parcel N<sup>o</sup> G 2102100200  
Part SW 1/4 & W 1/2 SE 1/4 Sec. 21, T-5-S,  
R-5-E, Moulton Twp, Auglaize Co., OH



**KUCK and MORRISEY, INC.**  
CONSULTING ENGINEERS & SURVEYORS - LIMA, OHIO  
2807 Chapel Hill Drive, Lima, Ohio  
(419) 228-1735 Phone & Fax

Surveyed By:  
RDM  
Date:  
6/14/08

Q-118