


NAD83(2011).




## Legend

- A = Existing Monument Box at the NE Corner of Section 27
- B = Existing Monument Box at the SE Corner of Section 27
- C = Existing Concrete Monument
- D = Existing  $\frac{1}{2}$  Iron Pipe
- E = Existing #5 Rebar
- F = Existing Corner Post
- G = Set #5 Rebar
- = Benchmark, Set #5 Rebar with yellow cap stamped "Control Point" (Elevation = 903.75')


This plat is recorded in Survey Book "S", Pages 17-18, in the Auglaize County Engineer's Office.


## Note:

All distances shown are measured unless otherwise noted.



This plat and the accompanying legal descriptions represent an actual boundary survey completed under my direct supervision on February 11, 2015.





Jacob F. & Laura Eilerman Page 2 of 2 February 11, 2015

## **LEGAL DESCRIPTION**

Being a part of Parcel #K29-271-002-02 (Prior Deed Reference O.R. 634, Pg. 1231) and being a part of the SE ¼ of Section 27, Town 6 South, Range 4 East, St. Marys Township, Auglaize County, Ohio, more particularly described as follows:

Commencing at an Existing Monument Box at the SE corner of Section 27; thence N 00°-56′-08″ E with the E line of Section 27, 1,339.70′ to a #5 Rebar set at the POINT OF BEGINNING; thence the following courses:

- 1. N 83°-28'-21" W, 229.43' to a set #5 Rebar, passing a #5 Rebar set at 34.37';
- 2. N 15°-15'-50" W, 199.39' to an Existing ½" Iron Pipe;
- 3. S 87°-52′-36" E, 284.02' to a point on the E line of Section 27 as referenced by an Existing #5 Rebar at N 87°-52′-36" W, 0.13', passing a #5 Rebar at 259.02';
- 4. S 00°-56′-08" W with said fractional section line, 207.94' to the POINT OF BEGINNING;

The above described parcel contains 1.165 acres, more or less, of which 0.140 acres are occupied by road right-of-way, subject to all legal highways and easements of record.

The system of bearings for this legal description is based on the Ohio State Plane-North Coordinate System NAD83(2011). This legal description and accompanying plat represent an actual boundary survey completed under the direct supervision of Kyle J. Binkley, P.S. #8587 on February 11, 2015. All markers called for above are in place.



6/1-3-