


Survey of Parcel #H23-033-001-03 and part of Parcel #H23-033-001-00 and being a part of the W $\frac{1}{2}$ of the NE $\frac{1}{4}$ of Section 33, Town 5 South, Range 4 East, Noble Township, Auglaize County, Ohio. (Prior Deeds Referenced in O.R. 645, Pg. 1954 & O.R. 546, Pg. 132)

Legend

- A = Existing Monument Box on the N line of Section 33 and being at the intersection of centerlines of State Route 116 and Markley Road
- B = Existing Monument Box at the intersection of the S line of the NE $\frac{1}{4}$ of Section 33 and the centerline of State Route 116
- C = Existing Railroad Spike
- D = Existing #5 Rebar
- E = Set Mag Nail
- F = Set #5 Rebar

This plat is recorded in Survey Book "S", Page 366, in the Auglaize County Engineer's Office.

Surveyor's Note: The original survey shown for Parcel "A", as shown in Survey A-202 of the Auglaize County Tax Map Office, has an error in closure of 35.07'. This survey is based on the existing monumentation found.





This plat and the accompanying legal descriptions represent an actual boundary survey completed under my direct supervision on April 15, 2016.

Kyle J. Binkley, P.S. #8587



121 W. Auglaize Street Wapakoneta, Ohio 45895 (419) 236-3768

Ryan Santore K.J.B. 04-15-2016 K.J.B. K.J.B. SCALE OF PAGES 1'' = 50'

Parcel "A" LEGAL DESCRIPTION

Being Parcel #H23-033-001-03 (Prior Deed Reference in O.R. 645, Pg. 1954) and being a part of the W ½ of the NE ¼ of Section 33, Town 5 South, Range 4 East, Noble Township, Auglaize County, Ohio, more particularly described as follows:

Commencing at an Existing Monument Box on the N line of Section 33 and being the intersection of centerlines of State Route 116 and Markley Road; thence S 19°-33'-27" E with the centerline of State Route 116, 790.48' to an existing Railroad Spike at the POINT OF BEGINNING; thence the following courses:

- 1. S 19°-33'-27" E continuing with said centerline, 168.06' to an existing Railroad Spike;
- 2. S 80°-10'-54" W, 239.08' to an existing #5 Rebar, passing a set #5 Rebar at 30.44';
- 3. N 09°-50′-49" W, 165.71' to an existing #5 Rebar;
- 4. N 80°-12'-08" E, 210.73' to the POINT OF BEGINNING, passing a set #5 Rebar at 180.35'.

The above described parcel contains 0.855 acres, more or less, of which 0.116 acres are occupied by road right-of-way, subject to all legal highways and easements of record.

The system of bearings for this legal description is based on the Ohio State Plane-North Coordinate System NAD83 (2011). This legal description and accompanying plat represent an actual boundary survey completed under the direct supervision of Kyle J. Binkley, P.S. #8587 on April 15, 2016. All markers called for above are in place.



1/1/3/20

Ryan Santore Page 3 of 3 April 15, 2016

Parcel "B" LEGAL DESCRIPTION

Being a part of Parcel #H23-033-001-00 (Prior Deed Reference in O.R. 546, Pg. 132) and being a part of the W $\frac{1}{2}$ of the NE $\frac{1}{2}$ of Section 33, Town 5 South, Range 4 East, Noble Township, Auglaize County, Ohio, more particularly described as follows:

Commencing at an Existing Monument Box on the N line of Section 33 and being the intersection of centerlines of State Route 116 and Markley Road; thence S 19°-33'-27" E with the centerline of State Route 116, 958.54' to an existing Railroad Spike at the POINT OF BEGINNING; thence the following courses:

- 1. S 19°-33'-27" E continuing with said centerline, 5.72' to a set Mag Nail;
- 2. S 79°-02'-28" W, 259.82' to a set #5 Rebar, passing a set #5 Rebar at 30.34';
- 3. N 06°-34′-01″ W, 10.82′ to an existing #5 Rebar;
- 4. N 80°-10'-54" E, 258.19' to the POINT OF BEGINNING, passing an existing #5 Rebar at 19.11' and passing a set #5 Rebar at 227.75'.

The above described parcel contains 0.049 acres, more or less, of which 0.004 acres are occupied by road right-of-way, subject to all legal highways and easements of record.

The system of bearings for this legal description is based on the Ohio State Plane-North Coordinate System NAD83 (2011). This legal description and accompanying plat represent an actual boundary survey completed under the direct supervision of Kyle J. Binkley, P.S. #8587 on April 15, 2016. All markers called for above are in place.



MI Jam