





20

Simon Muffer.  
Bluffs of  
Mill Pond

Survey of a piece of land, described as follows, beginning at the S. E. corner  
being on the South line) of the West half of the N. E. Quarter of section 28  
included in S. 5 S. of R. 7. E. of the first Meridian Ohio, and six chains west  
of the South East corner, of the South East corner of the aforesaid Quarter thence running  
according to the following Plot, & Notes. Surveyed by Simon Muffer May the 25th 1852.



| Sta | Bearing       | Dist | Remarks       | Dist |
|-----|---------------|------|---------------|------|
| 1   | Post          | —    | Corner        | —    |
| 2   | S. 53° 30' E. | 20   | N. 25° 30' W. | 36   |
| 3   | Beech         | 12   | S. 70° 10' W. | 32   |
| 4   | Wood Oak      | 36   | Corner        | —    |
| 5   | Post          | —    | Corner        | —    |
| 6   | Buckeye       | 11   | S. 23° E.     | 28   |
| 7   | S. Oak        | 16   | N. 43° E.     | 46   |
| 8   | Beech         | 5    | N. 24° W.     | 94   |
| 9   | Hickory       | 5    | Corner        | —    |
| 10  | W. Oak        | 6    | S. 10° E.     | 11   |
| 11  | Beech         | 6    | S. 44° W.     | 71   |
| 12  | Stone         | —    | Corner        | —    |
| 13  | W. Oak        | 32   | N. 46° W.     | 53   |
| 14  | Post          | 5    | N. 18° E.     | 56   |
| 15  | Post          | —    | Corner        | —    |
| 16  | Post          | —    | Corner        | —    |
| 17  | Buckeye       | 10   | S. 9° W.      | 9    |
| 18  | Beech         | 12   | N. 22° W.     | 20   |
| 19  | Post          | —    | Corner        | —    |

| Sta | Bearings      | Dist | W. of Lot | Dist | N. W. W. | Dist      | Dist       |
|-----|---------------|------|-----------|------|----------|-----------|------------|
| 1   | S. 53° 30' E. | 3.90 | 2.32      | 5.13 | 3.13     | —         | 1. 21 16   |
| 2   | N. 75° 30' E. | 1.50 | .38       | 1.45 | 7. 11.   | 2. 72 98  |            |
| 3   | N. 52° 30' E. | 2.35 | 1.19      | 1.26 | 10. 42.  | 20. 73 58 |            |
| 4   | N. 55° 30' E. | 1.36 | .77       | 1.12 | 12. 50   | 5. 86 66  |            |
| 5   | N. 48° 30' E. | 3.42 | .30       | 3.61 | 17. 75.  | 5. 81 90  |            |
| 6   | S. 14° 30' E. | 3.15 | 3.05      | 77.  | 22. 53.  | —         | 65. 10 65  |
| 7   | S. 16° E.     | 4.23 | 2.94      | 3.05 | 26. 11.  | —         | 76. 93 28  |
| 8   | S. 9° 45' W.  | 7.50 | 7.39      | 1.27 | 27. 95.  | —         | 206. 550 5 |
| 9   | W. 107        | 5.70 | —         | 5.70 | 20. 18   | —         |            |
| 10  | N. 12° E.     | 3.18 | 3.69      | 75   | 15. 66   | 57. 78 54 |            |
| 11  | N. 29° W.     | 4.25 | 5.74      | 2.08 | 14. 56   | 53. 70 64 |            |
| 12  | S. 66° 30' W. | 6.10 | 2.67      | 6.14 | 6. 14    | —         | 16. 37 35  |
| 13  | North         | 7.50 | 7.50      | —    | —        | —         |            |

Containing 11.24 Acres

John B. Mather Surveyor

and December 18th 1852. Recorded December 18th 1852.